This report is not valid if the serial number has been defaced or altered

27088571

**IPN18C** 

## **ELECTRICAL INSTALLATION CONDITION REPORT**

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installatio

PART 1 : DETAILS OF THE CONTRACTOR, CLIENT AND INSTALL	ATION	
DETAILS OF THE CONTRACTOR  Registration No. 611074000 Branch No: .000  Trading Title: FPRO Electrical Services Ltd  Address: 83 Lingfield Road, East Grinstead  Postcode: RH19 2EP Tel No: .01342349646	DETAILS OF THE CLIENT  Contractor Reference Number (CRN): 202303202  Name: First Impressions  Address: Highgate Lodge, Highgate Works, Tomtits Lane, Forest Row, East Sussex  Postcode: RH18 5AT Tel No: N/A	DETAILS OF THE INSTALLATION  Occupier: Tenant  Address: Highgate Lodge, Highgate Works, Tomtits Lane, Forest Row, East Sussex  Postcode: RH18 5AT Tel No: N/A
PART 2 : PURPOSE OF THE REPORT		
Purpose for which this report is required: Periodic inspection and testing.  Date(s) when inspection and testing was carried out: 20/03/2023		ailable: (
PART 3 : SUMMARY OF THE CONDITION OF THE INSTALLATION	N	
General condition of the installation (in terms of electrical safety):  The electrical installation is in a good condition and it is safe for continuous conditions.  Estimated age of electrical installation: (25,, ) years  Evidence of		allation is: <b>Satisfactory/산작왕광선왕[청장(ory*</b> ( <i>delete as appropriate</i> )
PART 4: DECLARATION		
	THE APPROVED CONTRACTOR	

@ Copyright Certsure LLP (July 2018)

<sup>\*</sup>An unsatisfactory assessment indicates that dangerous (CODE C1) and/or potentially dangerous (CODE C2) conditions have been identified in PART 6, or that Further Investigation (CODE FI) without delay is required.



DART E · NEYT INCRECTION

This report is not valid if the serial number has been defaced or altered

27088571

IPN18C

# **ELECTRICAL INSTALLATION CONDITION REPORT**

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

TART J. NEAT INST ECTION		
I/We (as indicated on page 1) recommend, subject to the necessary remedial wo	rk being taken, this installation should be further inspected and tested after an interval of not more than 5	years/XXXXXX* (delete as appropriate)

Give reason for recommendation. Commercial property with electrical installation in a safe and good condition.

0.10.00	on for recommendation					***************************************							
PART 6	OBSERVATIONS AND RECOMMENDATIONS FOR ACTIONS TO BE TA	KEN											
CODES:	One of the following Codes, as appropriate, has been allocated to each of the observations made below to indicate to the person(s) responsible for the electrical installation the degree of urgency for remedial action	CODE FI 'Further Investigation Required'											
Referring	Referring to the Schedule of Items Inspected (see PART 10), the attached Schedule of Circuit Details and Test Results (see PART 12), and subject to any agreed limitations listed in PART 7:												
There ar	e no items adversely affecting electrical safety (), OR The following observ	ations and recommendations for action	are made:										
Item No		Observation(s)			Code	<b>Location Reference</b>							
()	(			)	()	()							
()	(			)	()	()							
()	(			)	()	()							
()	(			)	()	()							
()	(			)	()	()							
()	(			)	()	()							
()	(			)	()	()							
()	(			)	()	()							
()	(			)	()	()							
()	(			)	()	()							
()	(			)	()	()							
()	(			)	()	()							
()	(			)	()	()							
()	(			)	()	()							
()	(			)	()	()							
()	(			)	()	()							
()	(			)	()	()							
()	(			)	()	()							
Addition	Il pages? ( None State page numbers: ( N/A )			·									
1	e action required for items: ( N/A	) Improvem	ent recommended for items: (	N/A		)							
	medial action required for items: ( N/A		vestigation required for items: (	N/A		)							

<sup>\*</sup>The proposed date for the next inspection should take into consideration any legislative or licensing requirements and the frequency and quality of maintenance that the installation can reasonably be expected to receive during its intended life.

The period should be agreed between relevant parties.



This report is not valid if the serial number has been defaced or altered

27088571

**IPN18C** 

### **ELECTRICAL INSTALLATION CONDITION REPORT**

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

PART 7 : DETAILS AND LIMITATIONS OF THE INSPECTION AND TESTING													
The inspection and testing has been carried out in accordance with BS 7671: 2018, as amended. Cables concealed within trunking and conduits, or cables and conduits concealed under floors, in inaccessible roof spaces and generally within the fabric of the building or underground, have not been visually inspected unless specifically agreed between the Client and the Inspector prior to inspection.  Details of the installation covered by this report. The sub-main consumer unit of Highgate Lodge and the circuits supplied by them. Fixed wiring and accessories only.													
					(see additional p	age No. N/A							
Agreed limitations including the reasons, if any, on the inspection and testing: The additional protective, 30mA RCDs have only been tested at 1x I(n) due to the main fault protective, 100mA RCD installed at the origin.													
Agreed with (print name): JOHN GILL													
Extent of sampling: 20% sockets, 25% switch	Extent of sampling: 20% sockets, 25% switches and 15% light fittings (see additional page No. N/A												
Operational limitations including the reasons:					(see additional p	page No. N/A)							
PART 8: SUPPLY CHARACTERISTICS	AND EARTHING ARRANGEMENTS												
System type and earthing arrangements  TN-C-S: (N/A) TN-S: ()  Other (state): N/A  Supply protective device  (BS (EN) 1361)  Type: ( !!)	TT: (N/A) AC  DC  Confirmation of	rpe of live conductors  1-phase, 2-wire: (N/A)  3-phase, 3-wire: (N/A)  2-wire: (N/A)  3-p  4-wire: (N/A)  5-wire: (N/A)  6-wire: (N/A)  6-wire: (N/A)  6-wire: (N/A)  6-wire: (N/A)  6-wire: (N/A)	(400) V (230) V (50) Hz (0.69) kA *: (0.34) Ω	<sup>(1)</sup> By enquiry, measurement, or by calculation									
PART 9 : PARTICULARS OF INSTALLAT	TION REFERRED TO IN THIS REPORT												
Means of Earthing  Distributor's facility: (	Main protective conductors  Earthing conductor:  (material .Copper	Gas installation pipes: (N. Structural steel: () Oil installation pipes: (N. Lightning protection: (N. N. Structural steel)	Type:  /A) Location:  //A) No. of poles:  //A) Current rating	(4)		) ( <sup>N/A</sup> ) A (400) V							
Location: (N/A	(material Copper csa 10 mm²)  Connection / continuity verified: ()	Other (state): N/A	RCD rated re	is used as the main switch sidual operating current, $I_{\Delta n}$ : erating time: (193) ms	Rated time delay:	(100s ) mA (500 ) ms							

All fields must be completed. Enter either, as appropriate: '✓' if Acceptable condition;

'N/A' if Not applicable;

'LIM' if a Limitation exists;

or Code appropriately - CODE 'C1', 'C2', 'C3' or 'FI' (codes to be recorded in PART 6, with additional comments (where appropriate) on attached numbered sheets)

<sup>\*</sup>Where the installation is supplied by more than one source, the higher or highest values of prospective fault current,  $l_{pf}$ , and external earth fault loop impedance,  $Z_e$ , must be recorded.

Original (to the person

**APPROVED** CONTRACTOR

All fields must be completed. Enter either, as appropriate: '✓' if Acceptable condition; 'N/A' if Not applicable;

'LIM' if a Limitation exists;

or Code appropriately - CODE 'C1', 'C2', 'C3' or 'FI' (codes to be recorded in PART 6, with additional comments (where appropriate) on attached numbered sheets)

	- Issued in accordance with 25 757.1. 2510 Theyding	monto for Ziocanoai motamatione
PART 10 : SCHEDULE OF ITEMS INSPECTED		
<ul> <li>6.18 Provision of additional protection by an RCD not exceeding 30 mA</li> <li>a) For all socket-outlets with a rated current not exceeding 32 A, unless exempt:</li> <li>b) Supplies for mobile equipment with a rated current not exceeding 32 A for use outdoors:</li> <li>c) For cables concealed in walls / partitions at a depth of less</li> </ul>	() 6.27 Adequacy of connections, including cpcs, within accessories and to fixed and stationary equipment:  () 7. Isolation and switching 7.1 Isolators 8.2 Equipment does not constitute a fire hazard: 8.3 Enclosure not damaged / deteriorated so as to 8.4 Suitability for the environment and external	( <b>火</b> ) ( <b>火</b> ) impair safety: ( <b>火</b> )
than 50 mm:  d) For cables concealed in walls / partitions containing metal parts regardless of depth:  e) Circuits supplying luminaires within domestic (household) premises:	(	()
Note: Older installations designed prior to BS 7671: 2018 may not hat provided with RCDs for additional protection.  6.19 Provision of fire barriers, sealing arrangements and protection against thermal effects: 6.20 Band II cables segregated / separated from Band I cables: 6.21 Cables segregated / separated from non-electrical services: 6.22 Termination of cables at enclosures (indicate extent of sampling in PART 7 of report)  a) Connections under no undue strain: b) No basic insulation of a conductor, visible outside an enclosure: c) Connections of live conductors adequately enclosed: d) Adequacy of connection at point of entry to enclosure: 6.23 Temperature rating of cable insulation addequate: 6.24 Condition of accessories including socket-outlets, switches and joint boxes satisfactory: 6.25 Suitability of accessories for external influences:	f) Warning label posted in situations where live parts cannot a) Correct type of lamps fitted:	/ terminations: (N/A ) red by this report: (N/A )
PART 11 : SCHEDULES AND ADDITIONAL PAGES		
Schedule of Inspections Page No(s):  Schedule of Circuit for the installation Page No(s):  Page No(s):	t Details and Test Results  (6 None Page No(s):  The pages identified are an essential part of this report (see Regulation 653.2).  Additional pages, including data sheets (indicated in item 9. above) Page No(s):  (None Page No(s): Page No(s):  Continuation she (indicated in item 9. above) Page No(s): Page No(s):	( None ()

All fields must be completed. Enter either, as appropriate: '✓' if Acceptable condition;

'N/A' if Not applicable;

'LIM' if a Limitation exists;

or Code appropriately — CODE 'C1', 'C2', 'C3' or 'FI' (codes to be recorded in PART 6, with additional comments (where appropriate) on attached numbered sheets)

This report is not valid if the serial number has been defaced or altered

27088571

IPN18C

### **ELECTRICAL INSTALLATION CONDITION REPORT**

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

PART 12 : SCHEDULE OF CIRCUIT DETAILS AND TEST RESULTS					Circuits	Circuits/equipment vulnerable to damage when testing :																				
CODES for Type of wiring (A) Thermoplastic insulated / (B) Thermoplastic cables in metallic conduit (C) Thermoplastic cables in mon-metallic conduit					(D) Thermop	lastic cables in trunking (E) Thermoplas		oplastic cables in etallic trunking (F) Thermoplastic / SWA cables (G) Thermoplastic / SWA cables			(G) Thermo	mosetting / SWA cables (H) Mineral-insulated cables				(0) other - state: N/A										
J.	Circuit description	6	poq	erved		cuit ctor csa	tion 1)	F	Protective device			RCD			Circui	t impedanc	es (Ω)		Insul	ation resist	ance	Α.	earth nce, <i>Zs</i>	RCD operating	Te: butto	
Circuit number		Type of wiring (see Codes)	Reference Method (BS 7671)	Number of points served			ix. disconnection time ( <i>BS 7671</i> )	BS (EN)	Туре	Rating	Short-circuit capacity	Operating current, $l_{\Delta n}$	Maximum permir Zs for installe protective device	Ring (mea	final circuits	s only o end)	All circui (complete at one colur	least	Live / Live	Live / Earth	Test voltage DC	Polarity	Max. measured earth fault loop impedance, <i>Zs</i>	time		
		Ċ	Re	Numb	Live (mm <sup>2</sup> )	cpc (mm²)	(s) Max.	Δ.		(A)	ළි <sup>ප</sup> (kA)	(mA)	(Ω)	(Line)	(Neutral)	(cpc) r <sub>2</sub>	$(R_1 + R_2)$	$R_2$	(MΩ)	(MΩ)	(V)	(1)	[α] (Ω)	(ms)	RCD (✓)	AFDD (✔)
	RCD							61008	AC	80	6	30				_						1		28	~	
1	Sockets Room 1 & 8	Α	В	7	2.5	1.5	0.4	60898	В	32	6		1.37	0.41	0.41	0.66	0.27			999	500	1	0.74			
2	Lights & Sockets Room 4	Α	В	3	2.5	1.5	0.4	60898	В	20	6		2.19				0.65			999	500	1	1.10			
3	Lights & Sockets Room 3	А	В	3	2.5	1.5	0.4	60898	В	20	6		2.19				0.66			999	500	1	1.11			
4	Lights & Sockets Room 5	А	В	4	2.5	1.5	0.4	60898	В	20	6		2.19				0.62			999	500	1	1.05			
5	Lights & Sockets Room 2	Α	В	3	2.5	1.5	0.4	60898	В	20	6		2.19				0.53				500	1	0.98			
6	Heating	Α	В	1	2.5	1.5	0.4	60898	В	20			7.28				0.29				500		0.74			
7	Lights Room 1, 6, 7	Α	В	3	1.5	·	0.4	60898	В	6	6		7.28				0.85				500		1.30			
8	Emergency Lights	Α	В	3	1.5		0.4	60898	В	6	6		7.28				0.73				500		1.18			
9	Cooker	Α	В	1	6	2.5	0.4	60898	В	32	6		1.37				0.16			999	500	1	0.78			
						L	. 5							A N II C B 4 A	DTIN						00					
	STRIBUTION BOARD (DB) DETA be completed in every case)	ILS	DB desi Locatio	ignation n of DB	n: High	gate Lo gate Lo	dge Di dge		TESTI	ED BY		me (capi nature:	tals): FR/				Position: QS Date: 20/03/2023									
TO	BE COMPLETED ONLY IF THE	DB IS	S NOT	CONI	NECTE	D DIR	ECTLY	TO THE	ORIGI	N OF	THE IN	ISTALL	ATION				TEST IN	STRUN	VIENTS	(enter s	erial nun	nber a	against	each ins	trument	used)
Su	pply to DB is from: ( Highgate Main D	)B						)	Nomi	nal vol	tage: ( ?			f phases	:: ( 1	.)	Multi-fund (1015454				) (	Contir N/A	uity:			)
	ercurrent protection device for the dis														.193		Insulation N/A	resista	nce:		E		fault lo	op imped	lance:	
	Associated RCD (if any) Type: (BS EN 61008 ) No. of poles: (4 ) /Δπ (100s ) mA Operating time (193 ) ms  Characteristics at this DB Confirmation of supply polarity (194 ) Phase sequence confirmed (where appropriate); (NA ) 7 (0.63 ) Q / (0.44 ) kA																									

# **NOTES FOR RECIPIENT**

### THIS CONDITION REPORT IS AN IMPORTANT AND VALUABLE DOCUMENT WHICH SHOULD BE RETAINED FOR FUTURE USE

The purpose of periodic inspection is to determine, so far as is reasonably practicable, whether an electrical installation is in a satisfactory condition for continued service. This report provides an assessment of the condition of the electrical installation identified overleaf at the time it was inspected and tested, taking into account the stated extent of the installation and the limitations of the inspection and testing.

This report has been issued in accordance with the national standard for the safety of electrical installations, BS 7671: 2018 – Requirements for Electrical Installations.

The report identifies any damage, deterioration, defects and/or conditions found by the inspector which may give rise to danger (see PART 6), together with any items for which improvement is recommended.

If you were the person ordering this report, but not the user of the installation, you should pass this report, or a full copy of it including these notes, the schedules and additional pages (if any), immediately to the user.

This report should be retained in a safe place and shown to any person inspecting or undertaking further work on the electrical installation in the future. If you later vacate the property, this report will provide the new user with an assessment of the condition of the electrical installation at the time the periodic inspection was carried out.

Where the installation incorporates a residual current device (RCD) there should be a notice at or near the device stating that it should be tested every six months. For safety reasons it is important that this instruction is followed.

For safety reasons, the electrical installation should be re-inspected at appropriate intervals by a skilled person or persons, competent in such work. NICEIC\* recommends that you engage the services of an NICEIC Approved Contractor for the inspection.

The recommended date by which the next inspection should be carried out is stated in PART 5 of this report. There should also be a notice at or near the main switchboard or distribution board/consumer unit indicating when the next inspection of the installation is due.

Only an NICEIC Approved Contractor or Conforming Body is authorised to issue this NICEIC Electrical Installation Condition Report. You should have received the report marked 'Original' and the Approved Contractor should have retained the report marked 'Duplicate'.

This report form is intended to be issued only for the purpose of reporting on the condition of an existing electrical installation and must not be issued to certify new electrical installation work including the replacement of a distribution board or consumer unit.

The report consists of at least six numbered pages. Additional numbered pages may have been provided to permit further relevant information relating to the installation to be recorded. For installations having more than one distribution board or more circuits than can be recorded on PART 12, one or more additional *Schedules of Circuit Details and Test Results* should form part of the report. The report is invalid if any of the schedules identified in PART 10 are missing. The report has a printed serial number, which is traceable to the Contractor to which it was supplied.

PART 7 (Details and limitations) should identify fully the extent of the installation covered by this report and any limitations on the inspection and testing. The inspector should have agreed these aspects with the person ordering the report and with other interested parties (licensing authority, insurance company, mortgage provider and the like) before the inspection was carried out.

Operational limitations may have been encountered during the inspection such as inability to gain access to parts of the installation or to an item of equipment. The inspector should have noted any such limitations in PART 7. It should be noted that the greater the limitations applying to a report, the less its value from the safety aspect.

A declaration should have been given by the inspector in PART 4 of the report. The declaration must reflect the statement given in PART 3, which summarises the observations and recommendations made in PART 6. Where one or more observations have been made in PART 6, the Classification code given to each by the inspector indicates the degree of urgency with which remedial action needs to be taken to restore the installation to a safe working condition.

Where the inspector has indicated an observation as code C1 (danger present) the safety of those using the installation is at risk. Wherever practicable, items classified as (C1) should be made safe on discovery, and it is recommended that a skilled person(s) competent in electrical installation work undertakes the necessary remedial work immediately.

Where the inspector has indicated an observation as code C2 (potentially dangerous) the safety of those using the installation may be at risk, and it is recommended that a skilled person(s) competent in electrical installation work undertakes the necessary remedial work as a matter of urgency.

Where the inspector has indicated that an item requires further investigation (FI), the investigation should be carried out without delay to determine whether danger or potential danger exists. For further guidance on the Classification codes, please see the reverse of page 2.

Where the installation can be supplied by more than one source, such as the public supply and a standby generator or microgenerator, this should be identified in PART 8 Supply Characteristics and Earthing Arrangements, and the Schedules of Circuit Details and Test Results (PART 12) compiled accordingly.

Where inadequacies in the intake equipment have been observed (Item 1 of PART 10), the person ordering the inspection should inform the distributor and/or supplier as appropriate.

Should the person ordering this report have reason to believe that it does not reasonably reflect the condition of the electrical installation reported on, that person should in the first instance raise the specific concerns in writing with the Approved Contractor. If the concerns remain unresolved, the person ordering this report may make a formal complaint to NICEIC, for which purpose a complaint form is available on request.

The complaints procedure offered by NICEIC is subject to certain terms and conditions, full details of which are available upon application. NICEIC does not investigate complaints relating to the operational performance of electrical installations (such as lighting levels), or to contractual or commercial issues (such as time or cost).

\* NICEIC is operated by Certsure LLP, a partnership between the Electrical Contractors' Association and the charity, Electrical Safety First. NICEIC maintains and publishes registers of electrical contractors that it has assessed against particular scheme requirements (including the technical standard of electrical work).

For further information about electrical safety and how NICEIC can help you, visit **www.niceic.com** 

### **GUIDANCE FOR RECIPIENTS ON THE CLASSIFICATION CODES**

### Only one Classification code should be given for each recorded Observation

#### Classification code C1 (Danger present)

Where an observation has been given a Classification code C1, the safety of those using the installation is at risk and immediate remedial action is required.

The person responsible for the maintenance of the installation is advised to take action without delay to remedy the observed deficiency in the installation, or to take other appropriate action (such as switching off and isolating the affected part(s) of the installation) to remove the danger. The NICEIC Approved Contractor issuing this report will be able to provide further advice.

NICEIC makes available 'Electrical Danger Notification' forms to enable inspectors to record, and then to communicate to the person ordering the report, any dangerous condition discovered.

#### Classification code C2 (Potentially dangerous)

Classification code C2 indicates that, whilst those using the installation may not be at immediate risk, urgent remedial action is required to remove potential danger. The NICEIC Approved Contractor issuing this report will be able to provide further advice.

It is important to note that the recommendation given at PART 5 of this report (Next Inspection) for the maximum interval until the next inspection is conditional upon all items which have been given a Classification code C1 and code C2 being remedied immediately and as a matter of urgency, respectively.

It would not be reasonable for the inspector to indicate that the installation is in a satisfactory condition if any observation in this report has been given a code C1 or code C2 classification.

#### Classification code C3 (Improvement recommended)

Where an observation has been given a Classification code C3, the inspection and/or testing has revealed a non-compliance with the current safety standard which, whilst not presenting immediate or potential danger, would result in a significant safety improvement if remedied. Careful consideration should be given to the safety benefits of improving these aspects of the installation. The NICEIC Approved Contractor issuing this report will be able to provide further advice.

#### Code FI (Further investigation required without delay)

It should usually be possible for the inspector to attribute a Classification code to each observation without indicating a need for further investigation.

However, where 'FI' has been entered against an observation the inspector considers that further investigation of that observation is likely to reveal danger or potential danger that, due to the agreed extent or limitations of the inspection and/or testing, could not be fully identified at the time.

It would not be appropriate for the inspector to indicate that the installation is in a satisfactory condition if there is reasonable doubt as to whether danger or potential danger exists. Consequently, where the inspector has indicated 'Further investigation required without delay' (FI) the overall assessment of the installation (PART 3) should be marked as 'Unsatisfactory'.

If the inspector has indicated that an observation requires further investigation without delay, the person ordering this report is advised to arrange for the NICEIC Approved Contractor issuing the report (or another skilled person or persons competent in such work) to undertake further examination of that aspect of the installation as a matter of urgency, to determine whether or not danger or potential danger exists.

#### **Further information**

Further information on the application of Classification codes, primarily aimed at inspectors but of possible interest to persons ordering condition reports, can be found in Electrical Safety First's Best Practice Guide No 4 *Electrical installation condition reporting: Classification Codes for domestic and similar electrical installations*. The guide can be viewed or downloaded free of charge from www. electricalsafetyfirst.org.uk

For further information about electrical safety and how NICEIC can help you, visit www.niceic.com