

This report is not valid if the serial number has been defaced or altered

27087891

IPN18C

ELECTRICAL INSTALLATION CONDITION REPORT

PART 1 : DETAILS OF THE CONTRACTOR, CLIENT AND INSTALL	ATION	
DETAILS OF THE CONTRACTOR Registration No. 611074000 Trading Title: FPRO Electrical Services Ltd Address: 83 Lingfield Road, East Grinstead Postcode: RH19 2EP Tel No. 01342349646	DETAILS OF THE CLIENT Contractor Reference Number (CRN): 202303181 Name: First Impressions Address: Chaffinch Studio, Highgate Works, Tomtits Lane, Forest Row, East Sussex Postcode: RH18 5AT Tel No: N/A	DETAILS OF THE INSTALLATION Occupier: Tenant Address: Chaffinch Studio, Highgate Works, Tomtits Lane, Forest Row, East Sussex Postcode: RH18 5AT Tel No: N/A
PART 2: PURPOSE OF THE REPORT		
Purpose for which this report is required: Periodic inspection and testing. Date(s) when inspection and testing was carried out: (17/03/2023		railable: (
PART 3 : SUMMARY OF THE CONDITION OF THE INSTALLATION	N	
General condition of the installation (in terms of electrical safety): The electrical installation is in a good condition and it is safe for continuous conditions. (25) Estimated age of electrical installation: (25)		allation is: Satisfactory/산재왕좌범왕류정당tory* (<i>delete as appropriate</i>)
PART 4: DECLARATION		
	THE APPROVED CONTRACTOR	

^{*}An unsatisfactory assessment indicates that dangerous (CODE C1) and/or potentially dangerous (CODE C2) conditions have been identified in PART 6, or that Further Investigation (CODE FI) without delay is required.

This report is not valid if the serial number has been defaced or altered

27087891

IPN18C

ELECTRICAL INSTALLATION CONDITION REPORT

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

PART 5: NEXT INSPECTION

PART 6	OBSERVATIONS AND RECOMMENDATIONS FOR ACTIONS TO BE TAKE	N				
CODES:	One of the following Codes, as appropriate, has been allocated to each of the observations made below to indicate to the person(s) responsible for the electrical installation the degree of urgency for remedial action	CODE C1 'Danger Present' isk of injury. Immediate remedial action required	CODE C2 'Potentially Dangerous' Urgent remedial action required	CODE C3 'Improvement Recommended'	'Furth	CODE FI er Investigation Required'
	o the Schedule of Items Inspected (see PART 10), the attached Schedule of Circuit Details an			in PART 7:		
	no items adversely affecting electrical safety (), OR The following observation		are made:			
Item No		Observation(s)			Code	Location Reference
()	()	()	()
()	()	()	()
()	()	()	()
()	()	()	()
()	()	()	()
()	()	()	()
()	()	()	()
()	()	()	()
()	()	()	()
()	()	()	()
()	()	()	()
()	1)	()	()
()	1)	()	()
()	1)	()	()
()	1)	()	()
()					()	()
()	1			,	()	()
()	1			,	()	(
Δdditiona	pages? (None) State page numbers: (N/A)				(\/
	e action required for items: (N/A	\ mnrouome	ent recommended for items:	N/A		١
	nedial action required for items: (N/A		restigation required for items:			
orgent re	IICUIAI ACUUN ICUUNCU IUI ILCIIIS.	ruruler iliv	conganun reguneu ioi ilenis:	11/71		

^{*}The proposed date for the next inspection should take into consideration any legislative or licensing requirements and the frequency and quality of maintenance that the installation can reasonably be expected to receive during its intended life. The period should be agreed between relevant parties.



This report is not valid if the serial number has been defaced or altered

27087891

IPN18C

ELECTRICAL INSTALLATION CONDITION REPORT

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

PART 7 : DETAILS AND LIMITATIONS OF THE INSPECTION AND TESTING													
The inspection and testing has been carried out in accordance with BS 7671: 2018, as amended. Cables concealed within trunking and conduits, or cables and conduits concealed under floors, in inaccessible roof spaces and generally within the fabric of the building or underground, have not been visually inspected unless specifically agreed between the Client and the Inspector prior to inspection. Details of the installation covered by this report: The two sub-main consumer units of Chaffinch Studio and the circuits supplied by them. Fixed wiring and accessories only.													
Agreed limitations including the reasons, if any,	(see additional pa	ge No)											
Extent of sampling:	·	-											
PART 8: SUPPLY CHARACTERISTICS	AND EARTHING ARRANGEMENTS												
System type and earthing arrangements TN-C-S: (N/A) TN-S: (TT: (N/A) AC DC Confirmatio		(.	Nominal line voltage to Earth, U_0 (1): Nominal frequency, f (1): Prospective fault current, I_{pf} (1)*:	(400) V (230) V (50) Hz (0.73) kA (0.26) Ω	⁾ By enquiry, measurement, or by calculation							
PART 9 : PARTICULARS OF INSTALLAT	TION REFERRED TO IN THIS REPORT												
Means of Earthing Distributor's facility: (Main protective conductors Earthing conductor: (material	Gas installation pipes: Structural steel: Oil installation pipes: Lightning protection: Other (stetch)	Type: V/A Locatio V/A No. of V/A V/A Where	Fipoles: (4) Rating / s nt rating: (100) A Voltage ra e an RCD is used as the main switch	etting of device: ating:	(N/A) A							
Electrode resistance to Earth: $(NA) \Omega$	Connection / continuity verified:		Mosey	ated residual operating current, $I_{\Delta n}$: ured operating time: ($\stackrel{NA}{\dots}$) ms Rated tim	ne delay:	(N/A) mA (N/A) ms							

All fields must be completed. Enter either, as appropriate: '\script' if Acceptable condition; 'N/A' if Not applicable; 'LIM' if a Limitation exists; or Code appropriately - CODE 'United and the completed.

^{*}Where the installation is supplied by more than one source, the higher or highest values of prospective fault current, l_{pf} , and external earth fault loop impedance, Z_e , must be recorded.



ELECTRICAL INSTALLATION CONDITION REPORT

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

PART 10 : SCHEDULE OF ITEMS INSPECTED		
1. External condition of electrical intake equipment (visual inspection on		(N/A) 5.24 Single-pole switching or protective devices in line conductors only: $()$
(If inadequacies are identified with the intake equipment, it is recommend the person ordering the report informs the appropriate authority.)		.(N/A) 5.25 Protection against mechanical damage where cables enter equipment: ()
1.1 Service cable: (5.1 Adequacy of working space / accessibility of equipment: 5.2 Security of fixing:	() 5.26 Protection against electromagnetic effects where cables enter ferrromagnetic enclosures: () 6. Distribution / final circuits
2. Presence of adequate arrangements for parallel or switched alternative sources 2.1 Adequate arrangements where a generating set operates as a switched alternative to the public supply: 2.2 Adequate arrangements where generating set operates in parallel with the public supply: (N/A)	5.7 Enclosure not damaged / deteriorated so as to impair safety:	(
2.3 Presence of alternative / additional supply arrangement warning notice(s) at or near equipment, where required: (N/A)	5.9 Presence of main switch(es), linked where required:	() 6.5 Suitability of containment systems for continued use (including flexible conduit): ()
3. Automatic disconnection of supply 3.1 Main earthing and bonding arrangements a) Presence and condition of distributor's earthing arrangement: (5.13 RCD(s) provided for fault protection — includes RCBOs: 5.14 RCD(s) provided for additional protection — includes RCBOs: 5.15 RCD(s) provided for protection against fire — includes RCBOs: 5.16 Manual operation of circuit-breakers and RCDs to prove disconnection: 5.17 Confirmation that integral test button/switch causes RCD(s) to trip when operated (functional check) 5.18 Presence of RCD six-monthly retest notice at or near equipment, where required: 5.19 Presence of diagrams, charts or schedules at or near equipment where required: 5.20 Presence of non-standard (mixed) cable colour warning notice at or near equipment, where required:	() () () (
3.2 FELV a) Source providing at least simple separation: (N/A) b) Plugs, socket-outlets and the like not interchangeable with those of other systems within the premises: (5.23 Compatibility of protective device(s), base(s) and	() () () 6.15 Cable installation methods / practices appropriate to the type and nature of installation and external influences: () 6.16 Cables where exposed to direct sunlight, of a suitable type or adequately protected against solar radiation: () 6.17 Cables adequately protected against damage and abrasion: ()

All fields must be completed. Enter either, as appropriate: '✓' if Acceptable condition;

'N/A' if Not applicable;

'LIM' if a Limitation exists;

or Code appropriately - CODE 'C1', 'C2', 'C3' or 'FI' (codes to be recorded in PART 6, with additional comments (where appropriate) on attached numbered sheets)

Original (to the person ordering the work)

This report is not valid if the serial

number has been defaced or altered

ELECTRICAL INSTALLATION CONDITION REPORT

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

PART 10 : SCHEDULE OF ITEMS INSPECTED	
PART 10: SCHEDULE OF ITEMS INSPECTED 6.18 Provision of additional protection by an RCD not exceeding 30 mA a) For all socket-outlets with a rated current not exceeding 32 A, unless exempt: b) Supplies for mobile equipment with a rated current not exceeding 32 A for use outdoors: c) For cables concealed in walls / partitions at a depth of less than 50 mm: d) For cables concealed in walls / partitions containing metal parts regardless of depth: e) Circuits supplying luminaires within domestic (household) premises: Note: Older installations designed prior to BS 7671: 2018 may not have	6.26 Single-pole switching or protective devices in line conductors only: 6.27 Adequacy of connections, including cpcs, within accessories and to fixed and stationary equipment: 7. Isolation and switching 7.1 Isolators a) Presence and condition of appropriate devices: b) Acceptable location (local / remote): c) Capable of being secured in the OFF position: d) Correct operation verified: e) Clearly identified by position and / or durable markings: () 8. Current-using equipment (permanently connected) 8.1 Condition of equipment in terms of IP rating: 8.2 Equipment does not constitute a fire hazard: 8.3 Enclosure not damaged / deteriorated so as to impair safety: 8.4 Suitability for the environment and external influences: 8.5 Security of fixing: 8.6 Cable entry holes in ceiling above luminaires, sized or sealed so as to restrict the spread of fire: Circumpter does not constitute a fire hazard: 8.5 Security of fixing: 8.6 Cable entry holes in ceiling above luminaires, sized or sealed so as to restrict the spread of fire: Circumpter and location of luminaires inspected on a separate page: Page No. (N/A) 8.7 Recessed luminaires (e.g. downlighters)
provided with RCDs for additional protection. 6.19 Provision of fire barriers, sealing arrangements and protection against thermal effects: 6.20 Band II cables segregated / separated from Band I cables: 6.21 Cables segregated / separated from non-electrical services: 6.22 Termination of cables at enclosures (indicate extent of sampling in PART 7 of report) a) Connections under no undue strain: b) No basic insulation of a conductor, visible outside an enclosure: c) Connections of live conductors adequately enclosed: d) Adequacy of connection at point of entry to enclosure:	f) Warning label posted in situations where live parts cannot be isolated by the operation of a single device: 7.2 Switching off for mechanical maintenance a) Presence and condition of appropriate devices: () b) Acceptable location: c) Capable of being secured in the OFF position: d) Correct operation verified: e) Clearly identified by position and / or durable marking(s): e) Clearly identified by position and / or durable marking(s): b) Readily accessible for operation where danger might occur: b) Readily accessible for operation verified: c) Correct operation verified: c) Correct operation verified: c) Installed to minimise build-up of heat: c) No signs of overheating to surrounding building fabric: (N/A) No signs of overheating to conductors / terminations: (N/A) No signs of overheating to conductors / terminations: (N/A) No signs of overheating to conductors / terminations: (N/A) No signs of overheating to conductors / terminations: (N/A) No signs of overheating to conductors / terminations: (N/A) No signs of overheating to conductors / terminations: (N/A) No signs of overheating to conductors / terminations: (N/A) No signs of overheating to conductors / terminations: (N/A) No signs of overheating to conductors / terminations: (N/A) No signs of overheating to conductors / terminations: (N/A) No signs of overheating to conductors / terminations: (N/A) No signs of overheating to surrounding building fabric: (N/A) No signs of overheating to conductors / terminations: (N/A) No signs of overheating to conductors / terminations: (N/A) No signs of overheating to conductors / terminations: (N/A) No signs of overheating to surrounding building fabric: (N/A) No signs of overheating to surrounding building fabric: (N/A) No signs of overheating to surrounding building fabric: (N/A) No signs of overheating to surrounding building fabric: (N/A) No signs of overheating to surrounding building fabric: (N/A) No signs of overheating to surrounding building fabric: (N/A) No signs of overheating to surrounding building fa
PART 11 : SCHEDULES AND ADDITIONAL PAGES	T Signature.
Schedule of Inspections Page No(s): (etails and Test Results (6, 7

All fields must be completed. Enter either, as appropriate: '✓' if Acceptable condition;

'N/A' if Not applicable;

'LIM' if a Limitation exists;

or Code appropriately — CODE 'C1', 'C2', 'C3' or 'FI' (codes to be recorded in PART 6, with additional comments (where appropriate) on attached numbered sheets)

This report is not valid if the serial number has been defaced or altered

27087891

IPN18C

ELECTRICAL INSTALLATION CONDITION REPORT

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

PART 12 : SCHEDULE OF CIRCUIT DETAILS AND TEST RESULTS									Circuits/equipment vulnerable to damage when testing :																	
CODES for Type of wiring (A) Thermoplastic insulated / (B) Thermoplastic cables in metallic conduit (C) Thermoplastic cables in metallic conduit (C) Thermoplastic cables in monometallic conduit (I)										s in (E	Thermopla	istic cables ii lic trunking	n (F) The	ermoplastic /	SWA cables	(G) Thermo:	mosetting / SWA cables (H) Mineral-insulated cables				(0) other - state: N/A					
Je.	Circuit description	6	роц	served		cuit ctor csa	tion 1)	F	rotective	device		RCD	rmitted alled evice*		Circui	Circuit impedances (Ω)			Insu	lation resist	tance	, A	earth nce, <i>Zs</i>	RCD operating	Te: butti	
Circuit number		Type of wiring (see Codes)		Number of points served			Max. disconnection time (BS 7671)	BS (EN)	Туре	Rating	Short-circuit capacity	Operating current, $I_{\Delta n}$	Maximum permitted Z _S for installed protective device*	Ring final circuit (measured end t			All circuits (complete at least one column)		Live / Live	Live / Earth	Test voltage DC	Polarity	Max. measured earth fault loop impedance, <i>Z</i> s	time		
		,	Re	Numb	Live (mm ²)	cpc (mm ²)	(s)	Δ		(A)	پې (kA)	(mA)	(Ω)	(Line)	(Neutral)	(cpc) r ₂	$(R_1 + R_2)$	R_2	(MΩ)	(MΩ)	(V)	(1)	(Ω)	(ms)	RCD (✔)	AFDD (✔)
1	Outside light	А	В	1	1.5	1	0.4	60898	В	6	6		7.28				0.15	-		999	500	_	0.52			
	RCD							61008	AC	63	6	30										1		31.3	~	
2	Sockets	С	В	10	2.5	2.5	0.4	60898	С	32	6		0.68	0.50	0.49	0.49	0.38			999	500	1	0.52			
3	Central Heating	С	В	1	1.5		0.4	60898	В	20	6		2.19				0.46				500	1	0.60			
4	Lights - Front room	С	В	4	1.5	1.5	0.4	60898	С	6	6		3.64				0.42			999	500	1	0.66			
5	Lights - Back room	С	В	4	1.5	1.5	0.4	60898	С	6	6		3.64				0.78			999	500	1	0.92			
6	Lights - Toilet	С	В	2	1	1	0.4	60898	С	6	6		3.64				0.42			999	500	1	0.56			
	Floodlight	С	В	1	1.5	1.5	0.4	60898	С	6	6		3.64				0.29			999	500	V	0.44			
											-															
<u> </u>					Choff	finah D	D4						FD	A NIIZ NA /	DTIN						000					
l .	STRIBUTION BOARD (DB) DETA	ILS I	DB desi	ignatio	וומוו Chaft	finch St	tudio D I		TESTI	ED BY				AINK IVIA	ARTIN					Position						
(to	be completed in every case)		Locatio	n of DB	:						Sig	nature:	Jul-							Date:	8/03/20	23				
TO	BE COMPLETED ONLY IF THE	DB IS	S NOT	CON	NECTE	D DIR	ECTLY	TO THE	ORIGI	N OF	THE IN	ISTALL	ATION					NSTRU				nber	against	each ins	trument	used)
	pply to DB is from: (Rookery Main D											30) V	No. o	f phases	s: (1)	Multi-fu (10154	inction: 5411) (Contir N/A	nuity:)
Ove	ercurrent protection device for the dissociated RCD (if any) Type: (BS EN	stributi N/A	on circ	uit 7	Type: (B	S EN 60	1898 Nos. / N) /A \	Ratin	g: (63 ,) A		Oper	atina tim	, N/A			on resista) E				dance:	
Cha	aracteristics at this DB Confirmation of	of supply	y polarit	<i>)</i> :y: (¶	/) P	hase se	quence	confirmed (ا⁄ where a	approp	riate): (N	IA) 2	0,038 2 ₈ (.0.38) Ω	pf(0.61	.) kA	Earth el	ectrode ı	resistano	e:	F	RCD:				





This continuation sheet is not valid if the serial number is not the same as the corresponding certificate or report.

ISN18C

CONTINUATION SHEET:

ELECTRICAL INSTALLATION CERTIFICATES & ELECTRICAL INSTALLATION CONDITION REPORTS

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

XXX / IPN: SCHEDULE OF CIRCUIT DETAILS AND TEST RESULTS (Relate as appropriate)								Circuits/equipment vulnerable to damage when testing :																		
CO	DES for Type of wiring (A) Thermoplastic insulated sheathed cables	d / (B)	Thermoplas metallic cor	tic cables in nduit	(C)	hermoplastion	c cables in conduit	(D) Thermop	metallic trunking (-7 non-metallic trunking (-7								setting / SWA o	ables (H) Mineral-insu	ulated cables	(0) other - state: N/A					
-E	Circuit description		poq	served	Cir condu	rcuit ctor csa	tion (F	Protective device RCD P + 8 Circuit impedances				es (Ω)		Insu	ılation resis	tance	λ	earth nce, Zs	RCD operating	Test buttons					
Circuit number		Type of wiring (see Codes)	Reference Method (BS 7671)	Number of points served			Max. disconnection time (<i>BS 7671</i>)	BS (EN)	Туре	Rating	Short-circuit capacity	Operating current, $I_{\Delta n}$	Maximum permitted Z _S for installed protective device*	(mea	ı final circuit asured end t	to end)	All cir (complete one co	at least	Live / Live	Live / Earth	Test voltage DC	Polarity	Max. measured earth fault loop impedance, Zs	time	RCD	AFDD
			-	N N	Live (mm ²)	cpc (mm ²)	≥ (s)			(A)	(kA)	(mA)	(Ω)	(Line) r ₁	(Neutral) r _n	(cpc) r ₂	$(R_1 + R_2)$	R_2	(ΜΩ)	(MΩ)	(V)	(/)	(Ω)	(ms)	(V)	(V)
_	RCD	_		_				61008		63		30										V		31.3	~	
1	Sockets	С	В				0.4	60898	С	32	6			0.51	0.51	0.53	0.39			999	500		0.53			
2	Lights - Front row	C C	В	5 5	1.5		0.4	60898	С	6	6		3.64				0.36			999	500	_	0.50			
<u> </u>	Lights - Back row	C	В	5	1.5	1.5	0.4	60898	C	6	6		3.64				1.42			999	500	<i>'</i>	1.60			
			-												-											
			-												-											
			-												-											
			+												+											
	STRIBUTION BOARD (DB) DETA be completed in every case)	ILS	DB des Locatio	ignation n of DB	Chaff Chaff	inch DI	B2 udio		TEST	ED BY		me (capi nature:	tals): FR	ANK M	ARTIN					Position Date: .1.	QS 8/03/20	23				
TO	BE COMPLETED ONLY IF THE	DR IS	S NOT	CONI	VECTE	חות מי	FCTIV	TO THE	ORIGI	N OF	THE IN	ISTALI	ATION				TEST II	NSTRU	MENT	S (enter:	serial nui	nber	agains	t each ins	trument	used)
l .	pply to DB is from: (Rookery Main D	_)					No. o		s: (1	.)	Multi-fu	nction:			(Contir N/A	nuity:			,
1	ercurrent protection device for the dis										-	, •		p000	. ,		() ()
1	sociated RCD (if any) Type: (BS EN						oles: (-			Oper	ating tim	, N/A	\ ma	Insulation (N/A		ance:) (N/A		op impe)
Cha	aracteristics at this DB Confirmation o	of suppl	v polari) ty: (!) P	hase se	quence	confirmed (ر : where)	approbi	, IIIA iate): (IA)	oper 2 ₅ 0.41	aung um Ω	0.58		Earth eld	ectrode	resistan	ce:		RCD: N/A				
															-			, N/A)	•••••				1

NOTES FOR RECIPIENT

THIS CONDITION REPORT IS AN IMPORTANT AND VALUABLE DOCUMENT WHICH SHOULD BE RETAINED FOR FUTURE USE

The purpose of periodic inspection is to determine, so far as is reasonably practicable, whether an electrical installation is in a satisfactory condition for continued service. This report provides an assessment of the condition of the electrical installation identified overleaf at the time it was inspected and tested, taking into account the stated extent of the installation and the limitations of the inspection and testing.

This report has been issued in accordance with the national standard for the safety of electrical installations, BS 7671: 2018 – Requirements for Electrical Installations.

The report identifies any damage, deterioration, defects and/or conditions found by the inspector which may give rise to danger (see PART 6), together with any items for which improvement is recommended.

If you were the person ordering this report, but not the user of the installation, you should pass this report, or a full copy of it including these notes, the schedules and additional pages (if any), immediately to the user.

This report should be retained in a safe place and shown to any person inspecting or undertaking further work on the electrical installation in the future. If you later vacate the property, this report will provide the new user with an assessment of the condition of the electrical installation at the time the periodic inspection was carried out.

Where the installation incorporates a residual current device (RCD) there should be a notice at or near the device stating that it should be tested every six months. For safety reasons it is important that this instruction is followed.

For safety reasons, the electrical installation should be re-inspected at appropriate intervals by a skilled person or persons, competent in such work. NICEIC* recommends that you engage the services of an NICEIC Approved Contractor for the inspection.

The recommended date by which the next inspection should be carried out is stated in PART 5 of this report. There should also be a notice at or near the main switchboard or distribution board/consumer unit indicating when the next inspection of the installation is due.

Only an NICEIC Approved Contractor or Conforming Body is authorised to issue this NICEIC Electrical Installation Condition Report. You should have received the report marked 'Original' and the Approved Contractor should have retained the report marked 'Duplicate'.

This report form is intended to be issued only for the purpose of reporting on the condition of an existing electrical installation and must not be issued to certify new electrical installation work including the replacement of a distribution board or consumer unit.

The report consists of at least six numbered pages. Additional numbered pages may have been provided to permit further relevant information relating to the installation to be recorded. For installations having more than one distribution board or more circuits than can be recorded on PART 12, one or more additional *Schedules of Circuit Details and Test Results* should form part of the report. The report is invalid if any of the schedules identified in PART 10 are missing. The report has a printed serial number, which is traceable to the Contractor to which it was supplied.

PART 7 (Details and limitations) should identify fully the extent of the installation covered by this report and any limitations on the inspection and testing. The inspector should have agreed these aspects with the person ordering the report and with other interested parties (licensing authority, insurance company, mortgage provider and the like) before the inspection was carried out.

Operational limitations may have been encountered during the inspection such as inability to gain access to parts of the installation or to an item of equipment. The inspector should have noted any such limitations in PART 7. It should be noted that the greater the limitations applying to a report, the less its value from the safety aspect.

A declaration should have been given by the inspector in PART 4 of the report. The declaration must reflect the statement given in PART 3, which summarises the observations and recommendations made in PART 6. Where one or more observations have been made in PART 6, the Classification code given to each by the inspector indicates the degree of urgency with which remedial action needs to be taken to restore the installation to a safe working condition.

Where the inspector has indicated an observation as code C1 (danger present) the safety of those using the installation is at risk. Wherever practicable, items classified as (C1) should be made safe on discovery, and it is recommended that a skilled person(s) competent in electrical installation work undertakes the necessary remedial work immediately.

Where the inspector has indicated an observation as code C2 (potentially dangerous) the safety of those using the installation may be at risk, and it is recommended that a skilled person(s) competent in electrical installation work undertakes the necessary remedial work as a matter of urgency.

Where the inspector has indicated that an item requires further investigation (FI), the investigation should be carried out without delay to determine whether danger or potential danger exists. For further guidance on the Classification codes, please see the reverse of page 2.

Where the installation can be supplied by more than one source, such as the public supply and a standby generator or microgenerator, this should be identified in PART 8 Supply Characteristics and Earthing Arrangements, and the Schedules of Circuit Details and Test Results (PART 12) compiled accordingly.

Where inadequacies in the intake equipment have been observed (Item 1 of PART 10), the person ordering the inspection should inform the distributor and/or supplier as appropriate.

Should the person ordering this report have reason to believe that it does not reasonably reflect the condition of the electrical installation reported on, that person should in the first instance raise the specific concerns in writing with the Approved Contractor. If the concerns remain unresolved, the person ordering this report may make a formal complaint to NICEIC, for which purpose a complaint form is available on request.

The complaints procedure offered by NICEIC is subject to certain terms and conditions, full details of which are available upon application. NICEIC does not investigate complaints relating to the operational performance of electrical installations (such as lighting levels), or to contractual or commercial issues (such as time or cost).

* NICEIC is operated by Certsure LLP, a partnership between the Electrical Contractors' Association and the charity, Electrical Safety First. NICEIC maintains and publishes registers of electrical contractors that it has assessed against particular scheme requirements (including the technical standard of electrical work).

For further information about electrical safety and how NICEIC can help you, visit **www.niceic.com**

GUIDANCE FOR RECIPIENTS ON THE CLASSIFICATION CODES

Only one Classification code should be given for each recorded Observation

Classification code C1 (Danger present)

Where an observation has been given a Classification code C1, the safety of those using the installation is at risk and immediate remedial action is required.

The person responsible for the maintenance of the installation is advised to take action without delay to remedy the observed deficiency in the installation, or to take other appropriate action (such as switching off and isolating the affected part(s) of the installation) to remove the danger. The NICEIC Approved Contractor issuing this report will be able to provide further advice.

NICEIC makes available 'Electrical Danger Notification' forms to enable inspectors to record, and then to communicate to the person ordering the report, any dangerous condition discovered.

Classification code C2 (Potentially dangerous)

Classification code C2 indicates that, whilst those using the installation may not be at immediate risk, urgent remedial action is required to remove potential danger. The NICEIC Approved Contractor issuing this report will be able to provide further advice.

It is important to note that the recommendation given at PART 5 of this report (Next Inspection) for the maximum interval until the next inspection is conditional upon all items which have been given a Classification code C1 and code C2 being remedied immediately and as a matter of urgency, respectively.

It would not be reasonable for the inspector to indicate that the installation is in a satisfactory condition if any observation in this report has been given a code C1 or code C2 classification.

Classification code C3 (Improvement recommended)

Where an observation has been given a Classification code C3, the inspection and/or testing has revealed a non-compliance with the current safety standard which, whilst not presenting immediate or potential danger, would result in a significant safety improvement if remedied. Careful consideration should be given to the safety benefits of improving these aspects of the installation. The NICEIC Approved Contractor issuing this report will be able to provide further advice.

Code FI (Further investigation required without delay)

It should usually be possible for the inspector to attribute a Classification code to each observation without indicating a need for further investigation.

However, where 'FI' has been entered against an observation the inspector considers that further investigation of that observation is likely to reveal danger or potential danger that, due to the agreed extent or limitations of the inspection and/or testing, could not be fully identified at the time.

It would not be appropriate for the inspector to indicate that the installation is in a satisfactory condition if there is reasonable doubt as to whether danger or potential danger exists. Consequently, where the inspector has indicated 'Further investigation required without delay' (FI) the overall assessment of the installation (PART 3) should be marked as 'Unsatisfactory'.

If the inspector has indicated that an observation requires further investigation without delay, the person ordering this report is advised to arrange for the NICEIC Approved Contractor issuing the report (or another skilled person or persons competent in such work) to undertake further examination of that aspect of the installation as a matter of urgency, to determine whether or not danger or potential danger exists.

Further information

Further information on the application of Classification codes, primarily aimed at inspectors but of possible interest to persons ordering condition reports, can be found in Electrical Safety First's Best Practice Guide No 4 *Electrical installation condition reporting: Classification Codes for domestic and similar electrical installations.* The guide can be viewed or downloaded free of charge from www. electricalsafetyfirst.org.uk

For further information about electrical safety and how NICEIC can help you, visit www.niceic.com